### **"THE NATIONAL PROPERTY SERVICE"**



**Shepherd Chartered Surveyors** 



27 FINGLEN CRESCENT TULLIBODY FK10 3GJ



### Energy performance certificate



### **Energy Performance Certificate (EPC)**

# Scotland

#### Dwellings

#### 27 FINGLEN CRESCENT, TULLIBODY, FK10 3GJ

Dwelling type:	Top-floor maisonette
Date of assessment:	22 September 2015
Date of certificate:	22 September 2015
Total floor area:	94 m²
Primary Energy Indicator:	154 kWh/m²/year


Reference number: Type of assessment: Approved Organisation: Main heating and fuel: 9500-8528-0829-5023-1153 RdSAP, existing dwelling Elmhurst Boiler and radiators, mains gas

#### You can use this document to:

#### · Compare current ratings of properties to see which are more energy efficient and environmentally friendly

#### Estimated energy costs for your home for 3 years\*

<sup>t</sup> based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



#### Current Potential Very environmentally friendly - lower CO<sub>2</sub> emissions (92 plus) A B (81-91) 76(69-80) C 76 (55-68) D) E (39-54 (21-38) F (1-20) G Not environmentally friendly - higher CO<sub>2</sub> emissions

#### **Energy Efficiency Rating**

£1,887

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band C (77)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

### Environmental Impact (CO<sub>2</sub>) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide  $(CO_2)$  emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band C (76)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

#### Top actions you can take to save money and make your home more efficient

There are currently no improvement measures recommended for your home.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

#### 27 FINGLEN CRESCENT, TULLIBODY, FK10 3GJ 22 September 2015 RRN: 9500-8528-0829-5023-1153

#### Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, insulated (assumed)	★★★★☆	★★★★☆
Roof	Pitched, insulated (assumed)	★★★★☆	★★★★☆
Floor	(another dwelling below)	—	
Windows	Fully double glazed	★★★☆☆	★★★☆☆
Main heating	Boiler and radiators, mains gas	★★★★☆	★★★★☆
Main heating controls	Programmer, room thermostat and TRVs	★★★★☆	★★★★☆
Secondary heating	None	—	_
Hot water	From main system	★★★★☆	★★★★☆
Lighting	Low energy lighting in all fixed outlets	****	*****

#### The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

#### The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 27 kg  $CO_2/m^2/yr$ .

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 2.5 tonnes of carbon dioxide every year. You could reduce emissions by switching to renewable energy sources.

#### 27 FINGLEN CRESCENT, TULLIBODY, FK10 3GJ 22 September 2015 RRN: 9500-8528-0829-5023-1153

Estimated energy c	osts for this home		
	Current energy costs	Potential energy costs	Potential future savings
Heating	£1,338 over 3 years	£1,338 over 3 years	
Hot water	£354 over 3 years	£354 over 3 years	Niet en vliegelie
Lighting	£195 over 3 years	£195 over 3 years	Not applicable
Totals	£1,887	£1,887	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

**Recommendations for improvement** 

None

#### 27 FINGLEN CRESCENT, TULLIBODY, FK10 3GJ 22 September 2015 RRN: 9500-8528-0829-5023-1153

#### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

#### Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	6,461	(468)	N/A	N/A
Water heating (kWh per year)	2,208			

#### About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:	Mr. Christopher Hunter
Assessor membership number:	EES/016138
Company name/trading name:	J & E Shepherd
Address:	13 Albert Square
	Dundee DD1 1XA
Phone number:	01382 200454
Email address:	c.hunter@shepherd.co.uk
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

#### Use of this energy performance information

This Certificate and Recommendations Report will be available to view online by any party with access to the report reference number (RRN) and to organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK Governments. If you are the current owner or occupier of this building and do not wish this data to be used by these organisations to contact you in relation to such initiatives, please opt out by visiting www.scottishepcregister.org.uk and your data will be restricted accordingly. Further information on this and on Energy Performance Certificates in general can be found at www.scotland.gov.uk/epc.

# Scottish Single Survey



### survey report on:

Property address	27 Finglen Crescent Tullibody FK10 3GJ
------------------	--

Customer	Ms C Russell

Customer address	27 Finglen Crescent Tullibody FK10 3GJ
------------------	--

Prepared by     J & E Shepherd
--------------------------------

Date of inspection	22nd September 2015
--------------------	---------------------



### PART 1 - GENERAL

#### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property<sup>1</sup>.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

#### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

<sup>&</sup>lt;sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

#### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:-

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### **1.4 GENERIC MORTGAGE VALUATION REPORT**

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report<sup>2</sup> will be from information contained in the Report and the generic Mortgage Valuation Report.

<sup>&</sup>lt;sup>2</sup>Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

#### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

#### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

#### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### **1.10 DEFINITIONS**

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

### **PART 2 - DESCRIPTION OF THE REPORT**

#### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

#### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1. <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2. <u>Category 2:</u> Repairs or replacement requiring future attention, but estimates are still advised.
- 3. <u>Category 1:</u> No immediate action or repair is needed.

#### WARNING:

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

#### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

#### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

#### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

#### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value, the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

#### 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The subject property comprises a first and second floor duplex flat within a three storey block.
Accommodation	Ground floor: Entrance hall.
	First floor: Internal hallway, kitchen, dining room, two bedrooms, shower room with wc.
	Second floor: Living room.

Gross internal floor area (m²)	94sqm or thereby.

dev	subjects are situated within an established modern residential elopment of mixed style properties, lying on the outskirts of a and convenient for local shopping, educational and social ities.
-----	--

Age 1997 approximately.	
-------------------------	--

Weather	Dry and sunny	
Chimney stacks	None.	

Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.
	If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
	The roof is pitched and tiled with tiled ridge sections. No access hatch for the roof void area was present.

PVC gutters and downpipes.         Main walls       Visually inspected with the aid of binoculars where appropriate.         Foundations and concealed parts were not exposed or inspected.       The main walls appear to be of modern load bearing timber frame with a masonry external leaf.         Windows, external doors and joinery       Internal and external doors were opened and closed where keys were available.         Random windows were opened and closed where possible.       Doors and windows were not forced open.         Windows throughout are of a timber double glazed type with velux windows at second floor level. Front access door is of a timber and glazed type. There are timber soffit boards present.	Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
appropriate.       Foundations and concealed parts were not exposed or inspected.         The main walls appear to be of modern load bearing timber frame with a masonry external leaf.         Windows, external doors and joinery         Internal and external doors were opened and closed where keys were available.         Random windows were opened and closed where possible.         Doors and windows were not forced open.         Windows at second floor level.		PVC gutters and downpipes.
appropriate.       Foundations and concealed parts were not exposed or inspected.         The main walls appear to be of modern load bearing timber frame with a masonry external leaf.         Windows, external doors and joinery         Internal and external doors were opened and closed where keys were available.         Random windows were opened and closed where possible.         Doors and windows were not forced open.         Windows at second floor level.		
inspected.         The main walls appear to be of modern load bearing timber frame with a masonry external leaf.         Windows, external doors and joinery         Internal and external doors were opened and closed where keys were available.         Random windows were opened and closed where possible.         Doors and windows were not forced open.         Windows throughout are of a timber double glazed type with velux windows at second floor level. Front access door is of a timber	Main walls	
with a masonry external leaf.         Windows, external doors and joinery         Internal and external doors were opened and closed where keys were available.         Random windows were opened and closed where possible.         Doors and windows were not forced open.         Windows throughout are of a timber double glazed type with velux windows at second floor level. Front access door is of a timber		
keys were available.         Random windows were opened and closed where possible.         Doors and windows were not forced open.         Windows throughout are of a timber double glazed type with velux windows at second floor level. Front access door is of a timber		
keys were available.         Random windows were opened and closed where possible.         Doors and windows were not forced open.         Windows throughout are of a timber double glazed type with velux windows at second floor level. Front access door is of a timber		
Doors and windows were not forced open. Windows throughout are of a timber double glazed type with velux windows at second floor level. Front access door is of a timber	Windows, external doors and joinery	•
Windows throughout are of a timber double glazed type with velux windows at second floor level. Front access door is of a timber		Random windows were opened and closed where possible.
windows at second floor level. Front access door is of a timber		Doors and windows were not forced open.
		windows at second floor level. Front access door is of a timber

External decorations	Visually inspected.
	Painted timber finishes.

Conservatories / porches	None.

Communal areas	None.
Garages and permanent outbuildings	None.

Outside areas and boundaries	Visually inspected.
	It would appear the property benefits from a private allocated car-parking space, however, we recommend this be clarified.
	There are communal garden grounds to the rear elevation with a mixture of boundaries.
Ceilings	Visually inspected from floor level

Ceilings	Visually inspected from floor level.
	Presumed plasterboard ceilings throughout.

Internal walls	Visually inspected from floor level. Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	Internal walls are of plaster finishes.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.

	Floors throughout are of suspended timber variety.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.

Kitchen units were visually inspected excluding appliances.
The kitchen fittings are of wall and base type with worktop surface areas present. Internal doors, skirtings and facings are of a timber variety.

Chimney breasts and fireplaces	None.

Internal decorations	Visually inspected.
	Painted throughout.

Cellars	None.
---------	-------

Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Mains supply. Fuse board located in the entrance hallway at ground floor level.

Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Mains supply. Gas meter located externally.

Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation. No tests whatsoever were carried out to the system or appliances.
	Water is from the mains supply. Plumberwork, where seen, is of copper supply pipes and PVC wastepipes. The sanitary fittings comprise a three piece suite in the shower room.


Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	The property benefits from a gas fired central heating system, with the gas combination boiler located within the kitchen. It would appear that hot water is provided by the boiler.

Drainage	Drainage covers etc. were not lifted.
	Neither drains nor drainage systems were tested.
	Presumed to main public sewer.

Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	The property benefits from smoke alarms.

Any additional limits to inspection	For flats / maisonettes
	Only the subject flat and internal communal areas giving access to the flat were inspected.
	If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.
	The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.
	The property was fully floor covered and furnished at the time of inspection. The cupboards were full of possessions at the time of inspection. No access was afforded beneath the sanitary fittings. No access was afforded to any sub-floor areas. No access was afforded into the roof void area due to the lack of an access hatch. Roof decks were partially seen from ground floor level, however, it should be noted that no inspection of the rear roof pitch could take

place due to the lie of the land. A limited inspection for dampness was carried out due to the presence of furniture and possessions.
Although considerable care was taken during the course of our surface examination to detect defects serious in nature, we were unable to inspect those parts of the property which were covered, concealed or inaccessible and cannot therefore guarantee that any such parts of the property are entirely free from defect.
An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor.



#### 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	

Structural movement	
Repair category	1
Notes	No evidence of structural movement was noted at the time of inspection.

Dampness, rot and infestation	
Repair category	1
Notes	No dampness was noted at the time of inspection, however, not all areas could be tested due to the presence of furniture and possessions.

Chimney stacks	
Repair category	-
Notes	Not applicable.

Roofing including roof space	
Repair category	1
Notes	A heavily restricted inspection of the roof decks was carried out from street level only, however, no inspection of the rear roof pitch could take place due to the lie of the land. No access was afforded into the roof void area due to the lack of an access hatch.

Rainwater fittings	
Repair category	1
Notes	We recommend the rainwater goods be monitored under a heavy downpour to ensure they are free from defect, with any necessary remedial works being carried out thereafter. At the time of inspection the weather was dry following a dry spell. No evidence of leakage was noted.

Main walls	
Repair category	1
Notes	No serious defects noted.

Windows, external doors and joinery	
Repair category	1
Notes	Ongoing maintenance and repainting to the external timberwork should be anticipated in accordance with good maintenance practice.

External decorations	
Repair category	1
Notes	No serious defects noted.

Conservatories/porches	
Repair category	-
Notes	Not applicable.

Communal areas	
Repair category	-
Notes	Not applicable.

Garages and permanent outbuildings	
Repair category	-
Notes	Not applicable.

Outside areas and boundaries	
Repair category	1
Notes	The rear corner garden grounds lie immediately adjacent to a main road. A heavily restricted inspection of the boundaries was carried out due to mature growth.

Ceilings	
Repair category	1
Notes	Minor plaster cracking noted.

Internal walls	
Repair category	1
Notes	Minor plaster cracking noted.

Floors including sub-floors	
Repair category	1
Notes	Loose floorboards noted. No access was afforded to any sub-floor areas.

Internal joinery and kitchen fittings	
Repair category	1
Notes	No serious defects noted.

Chimney breasts and fireplaces	
Repair category	-
Notes	Not applicable.

Internal decorations	
Repair category	1
Notes	No serious defects noted.

Cellars	
Repair category	-
Notes	Not applicable.

Electricity	
Repair category	1
Notes	The Institution of Engineering and Technology recommends that inspection and testings are undertaken at least every 10 years and on a change of occupancy. It should be appreciated that only the most recently constructed or rewired properties will have installations which fully comply with present IET Regulations.

Gas	
Repair category	1
Notes	In the interests of safety and in light of recent regulations it would be prudent to have all gas appliances checked by a Gas Safe inspector/tradesman.

<b>F</b> Water, plumbing and bathroom fittings	
Repair category	2
Notes	No access was gained beneath the sanitary fittings and as such no comment can be made as to the condition of these areas. Discolouration noted to the sealants and grouting to the area adjacent to the shower. We recommend these areas be upgraded to ensure water tightness. Discolouration and softened timbers noted to the areas adjacent to the shower tray. It may be prudent to have these areas checked by a suitable contractor and quotes be obtained for any necessary remedial works.

Heating and hot water	
Repair category	1
Notes	It is assumed that the central heating system has been properly installed, updated and maintained to meet with all current regulations and standards with particular regard to fluing and ventilation requirements.

Drainage	
Repair category	1
Notes	All foul and surface water drainage is assumed to be to the main public sewer. The system was not tested.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	-
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	-
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	-
Internal decorations	1
Cellars	-
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	2
Heating and hot water	1
Drainage	1

#### **Category 3**

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

#### Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

#### Category 1

No immediate action or repair is needed.

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

#### 3. Accessibility information

#### Guidance notes on accessibility information

#### Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

#### Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground, first and second
2. Are there three steps or fewer to a main entrance door of the property?	Yes No X
3. Is there a lift to the main entrance door of the property?	Yes No X
4. Are all door openings greater than 750mm?	Yes No X
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes No X
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No

#### 4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

#### Matters for a solicitor or licensed conveyancer

A factoring charge may be in operation for upkeep of the communal areas, we recommend this be clarified prior to purchase.

Where defects or repairs have been identified within this report it is recommended that, prior to entering into any legally binding sale or purchase contract, further specialists or contractors advice and estimates should be obtained, to establish the implications, if any, on a potential offer to purchase or the sale price likely to be achieved for the property.

#### Estimated reinstatement cost for insurance purposes

For Reinstatement Cost Assessment purposes it is recommended that the subjects be insured for a sum of not less than £150,000 (ONE HUNDRED & FIFTY THOUSAND POUNDS) STERLING.

#### Valuation and market comments

Having considered matters, taking account of our general observations on site, we are of the opinion that the current market value of the subjects in their present condition and with the benefit of full vacant possession may be fairly stated in the capital sum of £115,000 (ONE HUNDRED & FIFTEEN THOUSAND POUNDS) STERLING.

Signed	Security Print Code [427761 = 6859 ] Electronically signed
Report author	Christopher Hunter
Company name	J & E Shepherd
Address	11 Gladstone Place, Stirling, FK8 2NN
Date of report	28th September 2015



Property Address					
Address Seller's Name Date of Inspection	27 Finglen Cresc Ms C Russell 22nd September		(10 3GJ		
Property Details					
Property Type	House X Purpose built flat	Bungalow	Purpose built maisonett	e Converted maisonette Flat over non-residential use Other (specify in General Remarks)	
Property Style	Detached Back to back	Semi detached	Mid terrace X Low rise block	End terrace     Other (specify in General Remarks)	
Does the surveyor be e.g. local authority, m		erty was built for	the public sector,	Yes X No	
Flats/Maisonettes onl	y Floor(s) on which	located Gr, 1&2		3 Lift provided? Yes X No	
Approximate Year of	Construction 1997	7			
Tenure					
X Absolute Ownership	Leasehold	Ground rent £	Unexpired y	/ears	
Accommodation					
Number of Rooms	2 Living room(s) 1 Bathroom(s)	2 Bedroom(s) 0 WC(s)	1       Kitchen(s)         0       Other (Specify in Generation)	eral remarks)	
Gross Floor Area (excluding garages and outbuildings) 94 m <sup>2</sup> (Internal) m <sup>2</sup> (External)					
Residential Element (	greater than 40%)	X Yes No			
Garage / Parking /	Outbuildings				
Single garage Available on site?	Double garage	X Parki	ing space	] No garage / garage space / parking space	
Permanent outbuildin	gs:				

Construction							
Walls	Brick	Stone	Concrete	X Timber frame	Othe	er (specify in Ger	eral Remarks)
Roof	X Tile	Slate	Asphalt	Felt	Othe	er (specify in Ger	eral Remarks)
Special Risks							
Has the property	suffered stru	ctural movem	ent?			Yes	X No
If Yes, is this rece	ent or progree	ssive?				 Yes	No
Is there evidence, immediate vicinity	•	eason to antio	cipate subsidence	e, heave, landslip	or flood in the	e Yes	XNo
If Yes to any of th	e above, pro	ovide details ir	n General Remar	<b>(</b> S.			
Service Connec	ctions						
Based on visual in of the supply in G			vices appear to be	e non-mains, plea	se comment	on the type a	Ind location
Drainage	X Mains	Private	None	Water	X Mains	Private	None
Electricity	X Mains	Private	None	Gas	X Mains	Private	None
Central Heating	X Yes	Partial	None				
Brief description of	of Central He	eating:					
Gas fired to stee	el panel radia	itors.					
Site							
Apparent legal iss	sues to be ve	rified by the c	conveyancer Ple	ase provide a brie	of description	in General R	emarks
Rights of way	_	rives / access		amenities on separat		ared service conr	
Ill-defined boundar			Iltural land included w			er (specify in Ge	
Location							
X Residential suburb	) 🗌 R	esidential within	town / city 🗌 Mix	ed residential / comme	ercial 🗌 Mai	nly commercial	
Commuter village	R	emote village	Sol	ated rural property	Oth	er (specify in Ge	neral Remarks)
Planning Issue	S						
Has the property	been extend	ed / converte	d / altered?	Yes X No			
If Yes provide det	ails in Genei	ral Remarks.					
Roads							
X Made up road	Unmade ro	oad Partl	y completed new road	Pedestrian	access only	Adopted	Unadopted

#### General Remarks

A factoring charge may be in operation for upkeep of the communal areas, we recommend this be clarified prior to purchase.

At the time of inspection the general condition of the property appeared consistent with its age and type of construction and was generally found to be in fair order throughout.

A precautionary check of the areas beneath and adjacent to the shower cubicle may be advisable prior to purchase. Staining and softened timbers were noted to the skirtings adjacent to the shower tray. We would recommend the sealants and grouting within the shower be upgraded to ensure water tightness.

#### **Essential Repairs**

None.			
Estimated cost of essential repairs £	Retention recommended? Yes	X No	Amount £

#### **Comment on Mortgageability**

The property forms suitable security for mortgage purposes subject to the specific lending criteria or mortgage provider.	f any
Valuations	
Market value in present condition	£ 115000
Market value on completion of essential repairs	£
Insurance reinstatement value (to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)	£ 150000
Is a reinspection necessary?	Yes X No
Buy To Let Cases	
What is the reasonable range of monthly rental income for the property assuming a letting on a 6 month Short Assured Tenancy basis?	£ 550-600
Is the property in an area where there is a steady demand for rented accommodation of this type?	X Yes No

#### Declaration Signed Security Print Code [427761 = 6859 ] Electronically signed by:-Surveyor's name **Christopher Hunter** Professional qualifications MA (Hons) MRICS Company name J & E Shepherd Address 11 Gladstone Place, Stirling, FK8 2NN Telephone 01786 450438 Fax 01786 465063 Report date 28th September 2015



### **Property Questionaire**



Property address	27 FINGLEN CRESCENT
	TULLIBODY
	FK10 3GJ

Seller(s)	IAN & CAROL RUSSELL
-----------	---------------------

Completion date of property questionnaire	28 SEPTEMBER 2015
--	-------------------

#### Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

#### Information to be given to prospective buyer(s)

1.	Length of ownership				
	How long have you owned the property? 8				
2.	Council tax				
	Which Council Tax band is your property in? (Please tick one) $\square A \square B \square C \square D \square E \square F \square G \square H$				
3.	Parking				
	What are the arrangements for parking at your property? (Please tick all that apply)				
	• Garage				
	Allocated parking space				
	Driveway				
	Shared parking				
	On street				
	Resident permit				
	Metered parking				
	Other (please specify):				
4.	Conservation area				
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?				

5.	Listed buildings	
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	☐ Yes ⊠ No
6.	Alterations/additions/extensions	
a.	<ul> <li>(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?</li> <li><u>If you have answered yes</u>, please describe below the changes which you have made:</li> </ul>	□ Yes ⊠ No
	<ul><li>(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?</li><li>If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as</li></ul>	Yes No
	possible for checking. If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property? If you have answered yes, please answer the three questions below:	□ Yes ⊠ No
	(i) Were the replacements the same shape and type as the ones you replaced?	Yes No
	(ii) Did this work involve any changes to the window or door openings?	Yes No
	(iii) Please describe the changes made to the windows doors, or patio approximate dates when the work was completed):	doors (with
	Please give any guarantees which you received for this work to your so agent.	olicitor or estate

7.	Central heating	
a.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the hall and the bathroom). <u>If you have answered yes or partial</u> – what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).	⊠ Yes □ No □ Partial
	If you have answered yes, please answer the three questions below:(i)When was your central heating system or partial central heating2007	g system installed?
	<ul><li>(ii) Do you have a maintenance contract for the central heating system?</li><li>If you have answered yes, please give details of the company with which you have a maintenance contract:</li></ul>	□ Yes ⊠ No
	(iii) When was your maintenance agreement last renewed? (Please and year).	provide the month
8.	Energy Performance Certificate	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	⊠ Yes □ No
9.	Issues that may have affected your property	
a.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	□ Yes ⊠ No
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	□ Yes □ No
b.	Are you aware of the existence of asbestos in your property? If you have answered yes, please give details:	□ Yes ⊠ No

0.	Services			
. Pl	ease tick which services are cor	of the supplier:		
	Services			
	Gas or liquid petroleum gas	x	Scottish Pov	ver
	Water mains or private water supply	x		
	Electricity	x	Scottish Pov	ver
	Mains drainage	x		
	Telephone	x		
	Cable TV or satellite			
	Broadband			
		1		
	Is there a septic tank system If you have answered yes, ple	□ Yes ⊠ No		
	(iv) Do you have appropriate consents for the discharge from your septic tank?			☐ Yes ☐ No ☐ Don't Know
<ul> <li>(v) Do you have a maintenance contract for your septic tank?</li> <li><u>If you have answered yes</u>, please give details of the company with which you have a maintenance contract:</li> </ul>				Yes No

11.	Responsibilities for shared or common areas	
a.	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? <u>If you have answered yes</u> , please give details:	□ Yes ⊠ No □ Don't Know
ь.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas? If you have answered yes, please give details:	<ul><li>☐ Yes</li><li>☑ No</li><li>☑ Not applicable</li></ul>
с.	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	□ Yes ⊠ No
d.	Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries? <u>If you have answered yes</u> , please give details:	□ Yes ⊠ No
e.	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries? If you have answered yes, please give details:	□ Yes ⊠ No
f.	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately- owned.) If you have answered yes, please give details:	☐ Yes ⊠ No
12.	Charges associated with your property	
a.	Is there a factor or property manager for your property? <u>If you have answered yes</u> , please provide the name and address, and give details of any deposit held and approximate charges:	⊠ Yes □ No

b.	Is there a common buildings insurance policy? If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?	<ul> <li>Xes</li> <li>No</li> <li>Don't Know</li> <li>Xes</li> <li>No</li> <li>Don't Know</li> </ul>
с.	Please give details of any other charges you have to pay on a regular lupkeep of common areas or repair works, for example to a residents' a maintenance or stair fund.	
13.	Specialist works	
a.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? <u>If you have answered yes</u> , please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	□ Yes ⊠ No
b.	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property? If you have answered yes, please give details:	□ Yes ⊠ No
c.	<u>If you have answered yes</u> to 13(a) or (b), do you have any guarantees relating to this work? <u>If you have answered yes</u> , these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself <u>please write below</u> <u>who has these documents</u> and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by:	☐ Yes ☐ No

14.	Guarantees					
a.	Are there any guarantees or warranties for any of the following:					
		No	Yes	Don't know	With title deeds	Lost
(i)	Electrical work		$\boxtimes$			
(ii)	Roofing		$\boxtimes$			
(iii)	Central heating					
(iv)	National House Building Council (NHBC)					
(v)	Damp course					
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)					
b.	If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s): NHBC BUILDMARK COVER					
с.	Are there any outstanding claims under any of the guarantees listed above? If you have answered yes, please give details:				□ Yes ⊠ No	
15.	Boundaries					
	So far as you are aware, has any boundary of your property been moved in the last 10 years? If you have answered yes, please give details:				□ Yes ⊠ No □ Don't kn	low

16.	Notices that affect your property		
	In the past three years have you ever received a notice:		
a.	advising that the owner of a neighbouring property has made a planning application?	□ Yes ⊠ No	
b.	that affects your property in some other way?	□ Yes ⊠ No	
с.	that requires you to do any maintenance, repairs or improvements to your property?	□ Yes ⊠ No	
	<u>If you have answered yes to any of <math>a-c</math> above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.</u>		

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s) :

Date:

#### **Shepherd Offices**

Aberdeen: 01224 202800 Ayr: 01292 267987 Coatbridge: 01236 436561 Cumbernauld: 01236 780000 Dumbarton: 01389 731682 Dumfries: 01387 264333 Dundee: 01382 200454

East Kilbride: 01355 248535 Edinburgh: 0131 2251234 Falkirk: 01324 635999 Fraserburgh: 01346 517456 Forfar: 01307 466100 Galashiels: 01896 750150 Glasgow: 0141 3532080

Dunfermline: 01383 722337 Glasgow (Southside): 0141 649 8020 Greenock: 01475 730717 Hamilton: 01698 897548 Inverness: 01463 712239 Kilmarnock: 01563 520318 Kirkcaldy: 01592 205442 Livingston: 01506 416777 Montrose: 01674 676768

Motherwell: 01698 252229 Musselburgh: 0131 6533456 Paisley: 0141 8898334 Perth: 01738 638188 Peterhead: 01779 470766 Saltcoats: 01294 464228 St Andrews: 01334 477773 Stirling: 01786 450438







Tel: 0845 263 7995

www.shepherd.co.uk

Tel: 0845 263 7995