"THE NATIONAL PROPERTY SERVICE"



Shepherd Chartered Surveyors



2 WALLACE PLACE CAMBUSBARRON STIRLING FK7 9PB



Energy performance certificate



Energy Performance Certificate (EPC)

Dwellings

Scotland

2 WALLACE PLACE, CAMBUSBARRON, STIRLING, FK7 9PB

Dwelling type: Semi-detached house

Date of assessment:30 June 2016Date of certificate:04 July 2016Total floor area:89 m²

Primary Energy Indicator: 282 kWh/m²/year

Reference number: 8100-4508-0029-8276-1663 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst

Main heating and fuel: Boiler and radiators, mains


gas

You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

| Estimated energy costs for your home for 3 years* | £3,009 | See your recommendations |
|---|--------|--------------------------------|
| Over 3 years you could save* | £1,017 | report for more information |

^{*} based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (64)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (57)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

| Recommended measures | Indicative cost | Typical savings over 3 years | Available with Green Deal |
|--------------------------------------|-----------------|------------------------------|------------------------------|
| 1 Cavity wall insulation | £500 - £1,500 | £636.00 | ② |
| 2 Floor insulation (suspended floor) | £800 - £1,200 | £153.00 | \bigcirc |
| 3 Solar water heating | £4,000 - £6,000 | £102.00 | Ø |

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.



The Green Deal may allow you to make your home warmer and cheaper to run at no up-front capital cost. See your recommendations report for more details.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

| Element | Description | Energy Efficiency | Environmental |
|-----------------------|--|-------------------|---------------|
| Walls | Cavity wall, as built, no insulation (assumed) | *** | *** |
| Roof | Pitched, 250 mm loft insulation | **** | ★★★★ ☆ |
| Floor | Suspended, no insulation (assumed) | _ | _ |
| Windows | Fully double glazed | *** | ★★★☆☆ |
| Main heating | Boiler and radiators, mains gas | **** | ★★★★ ☆ |
| Main heating controls | Programmer, room thermostat and TRVs | **** | ★★★★ ☆ |
| Secondary heating | None | _ | _ |
| Hot water | From main system | **** | ★★★★ ☆ |
| Lighting | Low energy lighting in 90% of fixed outlets | **** | **** |

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 50 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 4.4 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 2.5 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

| | Current energy costs | Potential energy costs | Potential future savings |
|-----------|----------------------|------------------------|--------------------------|
| Heating | £2,490 over 3 years | £1,575 over 3 years | |
| Hot water | £327 over 3 years | £225 over 3 years | You could |
| Lighting | £192 over 3 years | £192 over 3 years | save £1,017 |
| Total | £3,009 | £1,992 | over 3 years |

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

| Recommended measures | | Indicative cost | Typical saving Rating after improvement | | improvement | Green |
|----------------------|------------------------------------|-----------------|---|--------|-------------|-------|
| Re | commended measures | indicative cost | per year | Energy | Environment | Deal |
| 1 | Cavity wall insulation | £500 - £1,500 | £212 | C 71 | D 68 | |
| 2 | Floor insulation (suspended floor) | £800 - £1,200 | £51 | C 72 | C 70 | |
| 3 | Solar water heating | £4,000 - £6,000 | £34 | C 74 | C 72 | |
| 4 | Replacement glazing units | £1,000 - £1,400 | £41 | C 75 | C 74 | |
| 5 | Solar photovoltaic panels, 2.5 kWp | £5,000 - £8,000 | £246 | B 85 | B 83 | |


Measures which have a green deal tick of are likely to be eligible for Green Deal finance plans based on indicative costs. Subsidy also may be available for some measures, such as solid wall insulation. Additional support may also be available for certain households in receipt of means tested benefits. Measures which have an orange tick may need additional finance. To find out how you could use Green Deal finance to improve your property, visit www.greenerscotland.org or contact the Home Energy Scotland hotline on 0808 808 2282.

Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

External insulation with cavity wall insulation

Choosing the right improvement package





About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Cavity wall insulation

Cavity wall insulation, to fill the gap between the inner and outer layers of external walls with an insulating material, reduces heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. The insulation material is pumped into the gap through small holes that are drilled into the outer walls, and the holes are made good afterwards. As specialist machinery is used to fill the cavity, a professional installation company should carry out this work, and they should carry out a thorough survey before commencing work to ensure that this type of insulation is suitable for this home and its exposure. They should also provide a guarantee for the work and handle any building standards issues. Further information about cavity wall insulation and details of local installers can be obtained from the Building Standards Division's section of the Scottish Government website (www.scotland.gov.uk/Topics/Built-Environment/Building/Building-standards/publications/pubguide/cavitywallinsul) or the National Insulation Association (www.nationalinsulationassociation.org.uk).

2 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check this with your local authority building standards department.

3 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

4 Replacement glazing units

Replacing existing double-glazed units with new high-performance units. Building regulations require that replacement glazing is to a standard no worse than previous and a building warrant is not required. Planning permission might be required for such work if a building is listed or within a conservation area so it is best to check with your local authority.

5 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

| Heat demand | Existing dwelling | Impact of loft insulation | Impact of cavity wall insulation | Impact of solid wall insulation |
|------------------------------|-------------------|---------------------------|----------------------------------|---------------------------------|
| Space heating (kWh per year) | 14,921 | N/A | (4,454) | N/A |
| Water heating (kWh per year) | 2,181 | | | |

Addendum

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Christopher Hunter

Assessor membership number: EES/016138
Company name/trading name: J & E Shepherd
Address: 13 Albert Square

Dundee DD1 1XA

Phone number: 01382 200454
Email address: c.hunter@shepherd.co.uk

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Opportunity to benefit from a Green Deal on this property

Under a Green Deal, the cost of the improvements is repaid over time via a credit agreement. Repayments are made through a charge added to the electricity bill for the property.

To see which improvements are recommended for this property, please turn to page 3. You can choose which improvements you want to install and ask for a quote from an authorised Green Deal provider. They will organise installation by an authorised Green Deal installer. If you move home, the responsibility for paying the Green Deal charge under the credit agreement passes to the new electricity bill payer.

For householders in receipt of income-related benefits, additional help may be available.

To find out more, visit www.greenerscotland.org or call 0808 808 2282.

Authorised home energy assessment

Finance at no upfront cost

Choose from authorised installers May be paid from savings in energy bills

Repayments stay with the electricity bill payer

Scottish Single Survey



survey report on:

| , I | |
|--------------------|--|
| Property address | 2 Wallace Place Cambusbarron Stirling FK7 9PB |
| | |
| Customer | Mr P Forsyth |
| | |
| Customer address | |
| | |
| | |
| | |
| | |
| Prepared by | J & E Shepherd |
| | |
| Date of inspection | 30th June 2016 |
| | |



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.



The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:-

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report ² will be from information contained in the Report and the generic Mortgage Valuation Report.

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2. Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3. Category 1: No immediate action or repair is needed.

WARNING:

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value, the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

| Description | The subject property comprises a two storey former Local Authority semi detached house. |
|--------------------------------|--|
| Accommodation | GROUND FLOOR:- Entrance Hallway, Living Room, Kitchen & Shower Room (with Wc). |
| | FIRST FLOOR:- Three Bedrooms. |
| Gross internal floor area (m²) | 89m² or thereby. |
| Neighbourhood and location | The subjects are situated in an established residential area of mixed style properties lying within the commuter village of Cambusbarron and convenient for local shopping, educational and social facilities. |
| Age | 1947 approximately. |
| Weather | Dry but overcast. |
| Chimney stacks | Visually inspected with the aid of binoculars where appropriate. |
| | Chimneys are of rendered masonry construction. |
| Roofing including roof space | Sloping roofs were visually inspected with the aid of binoculars where appropriate. |
| | Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. |
| | If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so. |
| | The roof is timber framed, pitched and overlaid in tiles with tiled roof |

| | sections. |
|-------------------------------------|---|
| | A head and shoulders access was afforded into the roof void area via an access hatch within the first floor hall ceiling. |
| | |
| Rainwater fittings | Visually inspected with the aid of binoculars where appropriate. |
| | Cast iron gutters and downpipes. |
| Main walls | Visually inspected with the aid of binoculars where appropriate. |
| | Foundations and concealed parts were not exposed or inspected. |
| | The main walls appear to be of traditional cavity brickwork having been roughcast externally. |
| | Evidence of cavity wall insulation was noted in the form of drill holes. |
| [| |
| Windows, external doors and joinery | Internal and external doors were opened and closed where keys were available. |
| | Random windows were opened and closed where possible. |
| | Doors and windows were not forced open. |
| | Windows throughout are of UPVC double glazed type. |
| | |
| | The front and rear access doors are of PVC type. |
| External decorations | Visually inspected. |
| External decorations | , · |
| | PVC finishes. |
| Conservatories / porches | Not applicable. |
| Communal areas | Not applicable. |
| Garages and permanent outbuildings | Not applicable. |
| Outside areas and boundaries | Visually inspected. |
| | The property benefits from garden ground to the front, side and rear elevations. |
| | Boundaries are defined by timber fencing. |
| | There is a driveway to the front/side elevation. |
| L | |

| Ceilings | Visually inspected from floor level. |
|---------------------------------------|--|
| | Presumed plasterboard ceilings throughout with Artex type finishes noted. |
| Internal walls | Visually inspected from floor level. |
| | Using a moisture meter, walls were randomly tested for dampness where considered appropriate. |
| | Internal walls have plasterboard finishes. |
| | |
| Floors including sub floors | Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted. |
| | Floors throughout are of suspended timber variety. |
| Internal joinery and kitchen fittings | Built-in cupboards were looked into but no stored items were moved. |
| | Kitchen units were visually inspected excluding appliances. |
| | Kitchen fittings are of wall and base type with worktop surface areas present. |
| | Internal doors, skirtings and facings are of a timber variety. |
| Chimney breasts and fireplaces | Visually inspected. |
| | No testing of the flues or fittings was carried out. |
| | The chimney breast within the living room has been capped. The fireplace has been temporarily covered over and an electric fire is currently in situ. |
| Internal decorations | Visually inspected. |
| | Papered and painted throughout. |
| | |
| Cellars | None. |
| Electricity | Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. Mains supply with fuseboard located in the hall cupboard. |

| services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. Mains supply with gas meter located externally. |
|---|
| Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation. |
| No tests whatsoever were carried out to the system or appliances. |
| Water is from the mains supply. |
| Plumberwork, where seen, is of copper supply pipes and PVC wastepipes. |
| Sanitary fittings comprise a three piece suite in the shower room. |
| Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. |
| No tests whatsoever were carried out to the system or appliances. |
| The property benefits from a gas fired central heating system with a gas combination boiler located in the hall cupboard. |
| Drainage covers etc. were not lifted. |
| Neither drains nor drainage systems were tested. |
| Drainage is presumed to be to the main public sewer. |
| Visually inspected. |
| No tests whatsoever were carried out to the system or appliances. |
| The property benefits from smoke alarms, however, these were not tested at the time of inspection. |
| For flats / maisonettes |
| Only the subject flat and internal communal areas giving access to the flat were inspected. |
| If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation. The building containing the flat, including any external |
| |

communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.

The property was fully floor covered and furnished at the time of inspection.

The cupboards were full of possessions at the time of inspection.

No access was gained beneath the sanitary fittings.

No access was gained to any sub-floor areas.

A head and shoulders inspection of the roof void area was undertaken only due to the lack of flooring, the presence of stored items and insulation materials. Not all areas of the roof void area could be seen from the access hatch.

A limited inspection for dampness was undertaken due to the presence of furniture and possessions.

Not all windows could be tested at the time of inspection due to furniture and blinds.

An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1) Chimney pots
- (2) Coping stone
- 3) Chimney head
- 4) Flashing
- (5) Ridge ventilation
- 6) Ridge board
- 7 Slates / tiles
- 8 Valley guttering
- 9 Dormer projection
- 10 Dormer flashing
- 11) Dormer cheeks
- (12) Sarking
- (13) Roof felt
- (14) Trusses
- 15) Collar
- (16) Insulation
- 17) Parapet gutter
- 18) Eaves guttering
- (19) Rainwater downpipe
- 0) Verge boards /skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- 24) Chimney breast
- (25) Window pointing
- S
- 26) Window sills
- (27) Rendering
- (28) Brickwork / pointing
- (29) Bay window projection
- 30 Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 33) Damp proof course
- 34) Base course
- 35) Foundations
- 36) Solum
- 37) Floor joists
- 8 Floorboards
- 9) Water tank
- (40) Hot water tank

2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

| Category 3 | Category 2 | Category 1 |
|------------|---|------------|
| | Repairs or replacement requiring future attention, but estimates are still advised. | |

| Structural movement | |
|---------------------|---|
| Repair category | 1 |
| Notes | No evidence of structural movement was noted at the time of inspection. |

| Dampness, rot and infestation | |
|-------------------------------|---|
| Repair category | 1 |
| Notes | No evidence of dampness was noted at the time of inspection, however, not all areas could be tested due to the presence of furniture and possessions. |

| Chimney stacks | |
|-----------------|---|
| Repair category | 1 |
| Notes | From a limited street level inspection chimney stacks appeared in satisfactory condition. Due to the age and type of construction ongoing maintenance to the chimney |
| | stacks and flashings should be anticipated. |

| Roofing including roof space | |
|------------------------------|--|
| Repair category | 2 |
| Notes | The pitched and tiled roof appears original to the subject property and will now be of an age and type which will require regular and ongoing maintenance. |
| | Missing loose and cracked tiles were noted. |
| | Defective ridge pointing noted. |
| | A limited head and shoulders inspection of the roof void area was undertaken via an access hatch in the first floor hall landing. No full access could be gained due to the lack of flooring, the presence of stored items and insulation materials. |

| Evidence of woodworm infestation was noted to timbers within the roof void area, |
|--|
| however, this would appear to be historic. Checks should be made for any |
| previous treatment works that have been undertaken in the past. |

| Rainwater fittings | |
|--------------------|---|
| Repair category | 1 |
| Notes | No evidence of leakage was noted to the gutters and downpipes at the time of inspection, however, the weather was dry. It may be prudent to have the rainwater goods monitored under a heavy downpour to ensure they are free of defects. |

| Main walls | |
|-----------------|---|
| Repair category | 2 |
| Notes | Sections of missing and cracked render were noted. Evidence of cavity wall insulation was noted in the form of drill holes to the walls. We recommend that any documentation be obtained for these works prior to |
| | purchase. |

| Windows, external doors and joinery | |
|-------------------------------------|---|
| Repair category | 2 |
| Notes | Failed double glazed unit noted within the rear bedroom. The UPVC double glazed windows were seen to be of an age and type which will require regular and ongoing maintenance and periodic replacement in parts. |

| External decorations | |
|----------------------|---------------------------|
| Repair category | 1 |
| Notes | No serious defects noted. |

| Conservatories/porches | |
|------------------------|-----------------|
| Repair category | - |
| Notes | Not applicable. |

| Communal areas | |
|-----------------|-----------------|
| Repair category | - |
| Notes | Not applicable. |

| Garages and permanent outbuildings | |
|------------------------------------|-----------------|
| Repair category | - |
| Notes | Not applicable. |

| Outside areas and boundaries | |
|------------------------------|---|
| Repair category | 1 |
| Notes | Uneven and cracked slabs noted to the side and rear elevations. |
| | A small pond was noted in the rear garden and we recommend all necessary Health & Safety measures are taken in this regard. |
| | Not all areas of boundaries could be inspected due to heavy vegetation growth. |

| Ceilings | |
|-----------------|---------------------------------|
| Repair category | 1 |
| Notes | Artex type ceilings were noted. |

| Internal walls | |
|-----------------|---------------------------|
| Repair category | 1 |
| Notes | No serious defects noted. |

| Floors including sub-floors | |
|-----------------------------|---|
| Repair category | 1 |
| Notes | No serious defects noted. |
| | No access was gained to any sub-floor areas. |
| | Due to fixed floorcoverings not all areas of the flooring could be inspected. |

| Internal joinery and kitchen fittings | |
|---------------------------------------|--|
| Repair category | 2 |
| Notes | It is presumed that all glazing below 800mm is fitted with the appropriate safety glass. |
| | Missing handles noted to kitchen units. |
| | The kitchen was seen to be dated and future modernisation should be anticipated. |

| The ceiling within the kitchen cupboard may contain asbestos type materials, |
|--|
| however, this could not be confirmed from our inspection. It may be prudent to |
| have this checked by a specialist contractor. |

| Chimney breasts and fireplaces | |
|--------------------------------|--|
| Repair category | 1 |
| Notes | We presume all chimney breasts, fireplaces and flues will be checked and cleared prior to use and any boarded up fireplaces have been adequately vented. |

| Internal decorations | |
|----------------------|---------------------------|
| Repair category | 1 |
| Notes | No serious defects noted. |

| Cellars | |
|-----------------|-----------------|
| Repair category | - |
| Notes | Not applicable. |

| Electricity | |
|-----------------|---|
| Repair category | 2 |
| Notes | The electrical fuse box and wiring system were seen to be of a mixed variety. The Institution of Engineering and Technology recommends that inspection and testings are undertaken at least every 10 years and on a change of occupancy. It should be appreciated that only the most recently constructed or rewired properties will have installations which fully comply with present IET Regulations. |

| Gas | |
|-----------------|---|
| Repair category | 1 |
| Notes | In the interests of safety and in light of recent regulations it would be prudent to have all gas appliances checked by a Gas Safe inspector/tradesman. |

| Water, plumbing and bathroom fittings | | | | | |
|---------------------------------------|--|--|--|--|--|
| Repair category | 1 | | | | |
| Notes | No access was gained beneath the sanitary fittings and accordingly no comment can be provided on the condition of these areas. | | | | |
| | At the time of inspection the sealant and grouting adjacent to the sanitary fittings were seen to be in fair order. | | | | |

| Heating and hot water | | | | |
|-----------------------|--|--|--|--|
| Repair category | 1 | | | |
| Notes | It is assumed that the central heating system has been properly installed, updated and maintained to meet with all current regulations and standards with particular regard to fluing and ventilation requirements. We understand from the vendor that the gas combination boiler is on an annual service plan and we recommend that all documentation pertaining to these works be sought prior to purchase. | | | |

| Drainage | |
|-----------------|--|
| Repair category | 1 |
| Notes | All foul and surface water drainage is assumed to be to the main public sewer. The system was not tested. |

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

| Structural movement | 1 |
|---------------------------------------|---|
| Dampness, rot and infestation | 1 |
| Chimney stacks | 1 |
| Roofing including roof space | 2 |
| Rainwater fittings | 1 |
| Main walls | 2 |
| Windows, external doors and joinery | 2 |
| External decorations | 1 |
| Conservatories/porches | - |
| Communal areas | - |
| Garages and permanent outbuildings | - |
| Outside areas and boundaries | 1 |
| Ceilings | 1 |
| Internal walls | 1 |
| Floors including sub-floors | 1 |
| Internal joinery and kitchen fittings | 2 |
| Chimney breasts and fireplaces | 1 |
| Internal decorations | 1 |
| Cellars | - |
| Electricity | 2 |
| Gas | 1 |
| Water, plumbing and bathroom fittings | 1 |
| Heating and hot water | 1 |
| Drainage | 1 |

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

| 1. Which floor(s) is the living accommodation on? | Ground & First |
|--|----------------|
| 2. Are there three steps or fewer to a main entrance door of the property? | Yes X No |
| 3. Is there a lift to the main entrance door of the property? | Yes No X |
| 4. Are all door openings greater than 750mm? | Yes No X |
| 5. Is there a toilet on the same level as the living room and kitchen? | Yes X No |
| 6. Is there a toilet on the same level as a bedroom? | Yes X No |
| 7. Are all rooms on the same level with no internal steps or stairs? | Yes No X |
| 8. Is there unrestricted parking within 25 metres of an entrance door to the building? | Yes X No |

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

A Wc has been added to the rear bedroom. We understand from the vendor that this was undertaken in excess of 25 years ago and as such may be classed as a historic alteration.

Where defects or repairs have been identified within this report it is recommended that, prior to entering into any legally binding sale or purchase contract, further specialists or contractors advice and estimates should be obtained, to establish the implications, if any, on a potential offer to purchase or the sale price likely to be achieved for the property.

Estimated reinstatement cost for insurance purposes

For Reinstatement Cost Assessment purposes it is recommended that the subjects be insured for a sum of not less than £135,000 (ONE HUNDRED AND THIRTY FIVE THOUSAND POUNDS STERLING).

Valuation and market comments

Having considered matters, taking account of our general observations on site, we are of the opinion that the current market value of the subjects in their present condition and with the benefit of full vacant possession may be fairly stated in the capital sum of £135,000 (ONE HUNDRED AND THIRTY FIVE THOUSAND POUNDS STERLING).

| Signed | Security Print Code [457854 = 2693] Electronically signed | | | |
|----------------|--|--|--|--|
| Report author | Christopher Hunter | | | |
| Company name | J & E Shepherd | | | |
| Address | 11 Gladstone Place, Stirling, FK8 2NN | | | |
| Date of report | 4th July 2016 | | | |

Mortgage Valuation Report



| Property Address | |
|--|---|
| Address Seller's Name Date of Inspection | 2 Wallace Place, Cambusbarron, Stirling, FK7 9PB Mr P Forsyth 30th June 2016 |
| Property Details | |
| Property Type | X House Bungalow Purpose built maisonette Converted maisonette Purpose built flat Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks) |
| Property Style | □ Detached X Semi detached □ Mid terrace □ End terrace □ Back to back □ High rise block □ Low rise block □ Other (specify in General Remarks) |
| Does the surveyor be e.g. local authority, m | elieve that the property was built for the public sector, X Yes No illitary, police? |
| Flats/Maisonettes only Approximate Year of 0 | No. of units in block |
| Tenure | |
| X Absolute Ownership | Leasehold Ground rent £ Unexpired years |
| Accommodation | |
| Number of Rooms | 1 Living room(s) 3 Bedroom(s) 1 Kitchen(s) 1 Bathroom(s) 1 WC(s) 0 Other (Specify in General remarks) |
| | cluding garages and outbuildings) 89 m² (Internal) m² (External) (greater than 40%) X Yes No |
| Garage / Parking / 0 | Outbuildings |
| Single garage Available on site? Permanent outbuilding | □ Double garage |
| | |

Mortgage Valuation Report

| Construction | | | | | | | |
|---------------------------------------|-----------------|--------------------|-----------------------|------------------------|-----------------|--------------------|----------------|
| Walls | X Brick | Stone | Concrete | Timber frame | Othe | er (specify in Gen | eral Remarks) |
| Roof | X Tile | Slate | Asphalt | Felt | Othe | er (specify in Gen | eral Remarks) |
| Special Risks | | | | | | | |
| Has the property | suffered struct | ural moveme | ent? | | | Yes | X No |
| If Yes, is this rece | ent or progress | ive? | | | | Yes | No |
| Is there evidence, immediate vicinity | • | ason to antici | pate subsidenc | e, heave, landslip | or flood in the | e Yes | X No |
| If Yes to any of th | e above, prov | de details in | General Remar | ks. | | | |
| Service Connec | ctions | | | | | | |
| Based on visual ir of the supply in G | | | ces appear to b | e non-mains, plea | se comment | on the type a | nd location |
| Drainage | X Mains | Private | None | Water | X Mains | Private | None |
| Electricity | X Mains | Private | None | Gas | X Mains | Private | None |
| Central Heating | X Yes | Partial | None | | | | |
| Brief description of | of Central Hea | ting: | | | | | |
| Gas fired to stee | l panelled rad | iators. | | | | | |
| Site | | | | | | | |
| Apparent legal iss | sues to be veri | fied by the co | onveyancer. Ple | ease provide a brie | ef description | in General R | emarks. |
| Rights of way | Shared driv | - | | r amenities on separat | _ | red service conn | |
| Ill-defined boundar | ries | Agricult | tural land included v | • | | er (specify in Ge | |
| Location | | | | | | | |
| X Residential suburb | Res | idential within to | own / city | ed residential / comme | ercial Mai | nly commercial | |
| Commuter village | Rer | note village | Iso | ated rural property | Oth | er (specify in Ge | neral Remarks) |
| Planning Issues | s | | | | | | |
| Has the property I | | | / altered? | Yes X No | | | |
| Roads | | | | | | | |
| X Made up road | Unmade road | d Partly | completed new roa | d Pedestrian | access only | Adopted | Unadopted |

Mortgage Valuation Report

General Remarks

A Wc has been added to the rear bedroom. We understand from the vendor that this was undertaken in excess of 25 years ago and as such may be classed as a historic alteration.

Where defects or repairs have been identified within this report it is recommended that, prior to entering into any legally binding sale or purchase contract, further specialists or contractors advice and estimates should be obtained, to establish the implications, if any, on a potential offer to purchase or the sale price likely to be achieved for the property.

At the time of inspection the general condition of the property appears consistent with its age and type of construction and was generally found to be in fair order throughout with only routine repair and maintenance being required.

The pitched and tiled roof appears original to the subject property and will now be of an age and type which will require regular and ongoing maintenance. It may be prudent to have the roof checked by a suitable roofing contractor prior to purchase.

The electrical fuse box and wiring system were found to be of a mixed variety and it may be prudent to have this checked by a qualified electrician with any necessary upgrading works being carried out thereafter.

A failed double glazed unit noted within the rear bedroom will require to be upgraded.

| Essential Repairs | | | |
|---------------------------------------|-----------------------------|------|----------|
| None. | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Estimated cost of essential repairs £ | Retention recommended? Yes | X No | Amount £ |

Mortgage Valuation Report

| Comment on Mortgagea | bility | | | |
|--|--|--------|--|--|
| The property forms suitable mortgage provider. | le security for mortgage purposes subject to the specific lending criteria o | f any | | |
| Valuations | | | | |
| Market value in present condition Market value on completion of essential repairs Insurance reinstatement value (to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT) Is a reinspection necessary? £ 135,000 £ 135,000 £ 135,000 £ 135,000 | | | | |
| Buy To Let Cases | | | | |
| What is the reasonable rangementh Short Assured Tenan | ge of monthly rental income for the property assuming a letting on a 6 ncy basis? | £ | | |
| Is the property in an area w | here there is a steady demand for rented accommodation of this type? | Yes No | | |
| Declaration | | | | |
| Signed Surveyor's name | Security Print Code [457854 = 2693] Electronically signed by:- Christopher Hunter | | | |
| Professional qualifications | MA (Hons) MRICS | | | |
| Company name | J & E Shepherd | | | |
| Address 11 Gladstone Place, Stirling, FK8 2NN | | | | |
| Telephone 01786 450438 | | | | |
| Fax 01786 465063 | | | | |
| Report date | 4th July 2016 | | | |



Property Questionaire



| Property address | 2 Wallace Place Cambusbarron Stirling FK7 9PB |
|---|---|
| Seller(s) | Martin & Co |
| Completion date of property questionnaire | 5 th July 2016 |

Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

| 1. | Length of ownership | |
|----|--|-----------------|
| | How long have you owned the property? 24yrs | |
| 2. | Council tax | |
| | Which Council Tax band is your property in? (Please ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ | tick one) G |
| 3. | Parking | |
| | What are the arrangements for parking at your prop (Please tick all that apply) | erty? |
| | • Garage | |
| | Allocated parking space | |
| | • Driveway | |
| | Shared parking | |
| | On street | |
| | Resident permit | |
| | Metered parking | |
| | Other (please specify): | |
| 4. | Conservation area | |
| | Is your property in a designated Conservation Area (special architectural or historical interest, the charact appearance of which it is desirable to preserve or en | ter or |

| 5. | Listed buildings | |
|----|---|--------------------|
| | Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)? | ☐ Yes ☑ No |
| 6. | Alterations/additions/extensions | |
| a. | (i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)? | ⊠ Yes □ No |
| | <u>If you have answered yes</u> , please describe below the changes which you have made: | |
| | A wc has been put in bedroom 3 | |
| | (ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work? | ☐ Yes ☑ No |
| | If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking. | |
| | If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them: | |
| b. | Have you had replacement windows, doors, patio doors or double glazing installed in your property? | ⊠ Yes □ No |
| | If you have answered yes, please answer the three questions below: | |
| | (i) Were the replacements the same shape and type as the ones you replaced? | ⊠ Yes □ No |
| | (ii) Did this work involve any changes to the window or door openings? | ☐ Yes ☑ No |
| | (iii) Please describe the changes made to the windows doors, or patio approximate dates when the work was completed): | doors (with |
| | Please give any guarantees which you received for this work to your so agent. | olicitor or estate |

| 7. | Central heating | |
|----|--|-----------------------|
| a. | Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the hall and the bathroom). If you have answered yes or partial — what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air). gas — fired If you have answered yes, please answer the three questions below: | ⊠ Yes □ No □ Partial |
| | (i) When was your central heating system or partial central heating Dec 2008 | g system installed? |
| | (ii) Do you have a maintenance contract for the central heating system? If you have answered yes, please give details of the company with which you have a maintenance contract: | ⊠ Yes □ No |
| | (iii) When was your maintenance agreement last renewed?(Please pand year). Jan 2016 | provide the month |
| 8. | Energy Performance Certificate | |
| | Does your property have an Energy Performance Certificate which is less than 10 years old? | ⊠ Yes □ No |
| 9. | Issues that may have affected your property | |
| a. | Has there been any storm, flood, fire or other structural damage to your property while you have owned it? If you have answered yes, is the damage the subject of any outstanding insurance claim? | ☐ Yes ☑ No ☐ Yes ☐ No |
| b. | Are you aware of the existence of asbestos in your property? If you have answered yes, please give details: | ☐ Yes ☑ No |

| 10. | Services | | | | | |
|-----------|--|-------------------------------|---------------|--------------------|--|--|
| a. Pl | a. Please tick which services are connected to your property and give details of the supplier: | | | | | |
| | Services | | | | | |
| | Gas or liquid petroleum gas Sottish Pow | | | er | | |
| | Water mains or privatewater supply | er | | | | |
| | Electricity | | Scottish Powe | г | | |
| | Mains drainage Scottish Wa | | | Scottish Water Sky | | |
| Telephone | | Sky | | | | |
| | Cable TV or satellite Sky | | | | | |
| | Broadband | | Sky | | | |
| , | | | | | | |
| b. | Is there a septic tank system a | at your property? | | ☐ Yes | | |
| | If you have answered yes, plea | ase answer the two quest | ions below: | ⊠ No | | |
| | (iv) Do you have appropriate septic tank? | ☐ Yes ☐ No ☐ Don't Know | | | | |
| | (v) Do you have a maintenance contract for your septic tank? If you have answered yes, please give details of the company with which you have a maintenance contract: | | | ☐ Yes ☐ No | | |

| 11. | Responsibilities for shared or common areas | |
|-----|--|-----------------------------|
| a. | Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? If you have answered yes, please give details: | ☐ Yes ☑ No ☐ Don't Know |
| b. | Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas? If you have answered yes, please give details: | ☐ Yes ☑ No ☐ Not applicable |
| C. | Has there been any major repair or replacement of any part of the roof during the time you have owned the property? | ☐ Yes ☑ No |
| d. | Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries? If you have answered yes, please give details: | ☐ Yes ☑ No |
| e. | As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries? If you have answered yes, please give details: | ☐ Yes ☑ No |
| f. | As far as you are aware, is there a public right of way acrossany part of your property? (public right of way is a way overwhich the public has a right to pass, whether or not the land isprivately-owned.) If you have answered yes, please give details: | ☐ Yes ☑ No |
| 12. | Charges associated with your property | |
| a. | Is there a factor or property manager for your property? If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges: | ☐ Yes ☑ No |

| с. | Is there a common buildings insurance policy? If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges? Please give details of any other charges you have to pay on a regular lupkeep of common areas or repair works, for example to a residents' a maintenance or stair fund. | |
|-----|---|---------------|
| 13. | Specialist works | |
| a. | As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property. Woodworm in loft area, detected in 1991 when house was bought. | ⊠ Yes □ No |
| b. | As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property? If you have answered yes, please give details: In 1991Cannon Property Care treated woodworm in loft area | ⊠ Yes □ No |
| C. | If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work? If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourselfplease write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by: | ☐ Yes ☑ No |

| 14. | Guarantees | | | | | |
|-------|--|-------------|------------|---------------|------------------------|------|
| a. | Are there any guarantees or warranties for any of the following: | | | | | |
| | | No | Yes | Don't know | With title deeds | Lost |
| (i) | Electrical work | \boxtimes | | | | |
| (ii) | Roofing | | | | | |
| (iii) | Central heating | | | | | |
| (iv) | National House Building Council (NHBC) | | | | | |
| (v) | Damp course | | | | | |
| (vi) | Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy) | | | | | |
| b. | If you have answered 'yes' or 'with title decinstallations to which the guarantee(s) relations to which the guarantee(s) relations to which the guarantee(s) relationships with the guarantee of the control of the cont | | se give d | etails of | the work or | |
| c. | Are there any outstanding claims under any of the guarantees listed above? If you have answered yes, please give details: ☐ Yes ☐ No | | | | | |
| 15. | Boundaries | | | | | |
| | So far as you are aware, has any boundary moved in the last 10 years? If you have answered yes, please give deta | • | property l | peen | ☐ Yes ☑ No ☐ Don't kne | ow |

| 16. | Notices that affect your property | |
|------|--|--|
| | In the past three years have you ever received a notice: | |
| a. | advising that the owner of a neighbouring property has made a planning application? | ☐ Yes ☑ No |
| b. | that affects your property in some other way? | ☐ Yes ☑ No |
| C. | that requires you to do any maintenance, repairs or improvements to your property? | ☐ Yes ☑ No |
| | If you have answered yes to any of a-c above, please give the notice estate agent, including any notices which arrive at any time before the purchaser of your property. | s to your solicitor of e date of entry of |
| I/W | aration by the seller(s)/or other authorised body or persone confirm that the information in this form is true and corpy/our knowledge and belief. | |
| Sign | ature(s): | |
| Date | e: | |

Shepherd Offices

Aberdeen: 01224 202800 Ayr: 01292 267987 Coatbridge: 01236 436561 Cumbernauld: 01236 780000 Dumbarton: 01389 731682

> Dumfries: 01387 264333 Dundee: 01382 200454

Dunfermline: 01383 722337 Glasgow (Southside): 0141 649 8020

East Kilbride: 01355 248535 Edinburgh: 0131 2251234 Falkirk: 01324 635999 Fraserburgh: 01346 517456

Galashiels: 01896 750150 Glasgow: 0141 3532080

Forfar: 01307 466100

Greenock: 01475 730717 Hamilton: 01698 897548 Inverness: 01463 712239

Kilmarnock: 01563 520318 Kirkcaldy: 01592 205442

Livingston: 01506 416777

Montrose: 01674 676768

Motherwell: 01698 252229

Musselburgh: 0131 6533456

Paisley: 0141 8898334 Perth: 01738 638188

Peterhead: 01779 470766 Saltcoats: 01294 464228

St Andrews: 01334 477773

Stirling: 01786 450438







Tel: 0845 263 7995

www.shepherd.co.uk

Tel: 0845 263 7995